

North America Emission Control Area Fuel Oil Non-Availability Report

Date of Issue

Field No	Field Name	
1	Report Form ID	ECA0100
2	Ship Operator Name	MUR SHIPPING BV
3	Vessel Name	Leo
4	Flag Country	MARSHALL ISLANDS
5	IMO ID Number	9594638
6	Date of ECA First Notice	6-Aug-13
7	Location of ECA First Notice	in Port of Huanghua/China
8	Name of Ports after First Notice	Portland Or/USA
9	Name of Last Port before ECA Entry	Huanghua/China
10	Name of Port with Fuel Oil Supply Disruption	NA
11	Name of Original Fuel Supplier with Disruption	NA
12	Number of Fuel Suppliers Contacted	We contact one bunker broker "Valhalla Marine Sarl" who contacted suppliers
13	Date of Entry in the ECA	on/about 27 Aug 2013
14	Time of Entry in the ECA	on/about 1800 hrs Local Time
15	Sulfur Content of Non-Compliant Fuel Oil	2.60%
16	Projected Hours on Main Propulsion	3
17	Name of First POC	Portland Or/USA
18	Compliance Fuel Oil Available at First POC?	Yes
19	Plan to Bunker Compliant Fuel Oil at First POC?	Yes
20	Number of fuel suppliers contacted at First POC	We Normally arrange supply via our bunker broker "LQM"
21	Name of Second POC	Vancouver BC/Canada
22	Compliant Fuel Oil at Second POC?	Yes
23	Plan to Bunker Compliance Fuel Oil at Second POC?	We will supply Compliant Fuel Oil at Portland Or upon arrival
24	Number of Fuel Suppliers Contacted at the Second POC?	
25	Date of Exit from ECA?	on/About 09 Sept 2013 After complete loading Portand Or & Vancouver BC
26	Time of Exit from ECA?	
27	Has this vessel operated in the ECA in previous 12 months?	No
28	Number of Separate Visits to the ECA	
29	Number of Ports visited in the ECA	
30	Previously submitted ECA0100 forms?	
31	Number of Submitted Reports	
32	Designated Corporate Official Name	Saad Adlach
33	Designated Corporate Official E-mail	ops.au@murship.com
34	Designated Corporate Official Phone Number	61-2-89125000
35	Description of Actions to Achieve Compliance	Once the voy details became known we have checked with bunker broker "Valhalla Marine Sarl" who advised that LSIFO (ECA Compliance Fuel) not available in Huanghua copy of the msg attached.

